





F/G. 2












FIG. 7

34

35

31

37









FIG. 9














FIG. 15






FIG. 16









FIG. 19







FIG. 21



0

SHAPES AND CRYSTALLINITY CONTROL

FIG. 22A

FIG. 22B

FIG. 22C

FIG. 22D

